TUMLINGTAR AIRPORT



Brief Description

Tumlingtar Airport is situated at Khandabari Municipality-9 of Sankhuwasabha District, Province No. 1. It is the gateway to Makalu - Barun National Park which is famous for its natural beauty and biodiversity. This Airport has a vital role for trade and tourism development as well as serves positive contribution to socio-economic development of the entire region.

General Information

| Name | TUMLINGTAR |
|----------------------------------|----------------------|
| Location Indicator | VNTR |
| IATA Code | TMI |
| Aerodrome Reference Code | 3C |
| Aerodrome Reference Point | 271902 N/0871143 E |
| Province/District | 1(One)/Sankhuwasabha |
| Distance and Direction from City | Amidst City |
| Elevation | 401 m. /1316 ft. |
| Contact | Off: 977- 29575207 |

| | Tower: 977-29575207 | | |
|-----------------------------|---|---------------|--|
| | Fax: 977-29575207 | | |
| | AFS: VNTRYDYX | | |
| | E-mail: tumlingtar_cao@caanepal.gov.np | | |
| Operation Hours | Nov 1 st to Jan 30 th (Kartik 16 th to Magh 15 th) | 1000LT-1600LT | |
| | Feb 1 st to Oct 30 th (Magh 16 th to Kartik 15 th) | 1000LT-1700LT | |
| Status | In Operation | | |
| Year of Start of Operation | 01 October, 1972 | | |
| Serviceability | All Weather | | |
| Land | Approx. 374427.35 m ² | | |
| Re-fueling Facility | Not Available | | |
| Service | AFIS | | |
| Type of Traffic Permitted | Visual Flight Rule (VFR) | | |
| Type of Aircraft | ATR42, JS41, B190, D228, DHC6, L410, Y12 | | |
| Schedule Operating Airlines | Buddha Air, Yeti Air | | |
| Schedule Connectivity | Kathmandu, Biratnagar | | |
| RFF | Available | | |

Infrastructure Condition

Airside

| Runway | Type of Surface | Bituminous Paved (Asphalt Concrete) |
|------------------|--|-------------------------------------|
| | Runway Dimension | 1295 m x 30 m |
| | Runway Designation | 16/34 |
| Parking Capacity | One ATR42, One Beechcraft and One JS41 | |
| Size of Apron | 5000 sq.m. | |
| Apron Type | Asphalt Concrete | |

Passenger Facilities


| Hotels | Yes (City Area) |
|-------------------|-----------------|
| Restaurants | Yes |
| Transportations | Jeep, Van |
| Banks/ATMs | Yes |
| Internet Facility | Wi-Fi |
| Cable TV | Yes |

Airport Facilities

| Console | One Man Position Tower Console with Associated Equipment and Accessories | | |
|--|--|------------------------------|--|
| Communication, Navigation & Surveillance Systems | | | |
| | Communication | HF SSB, VHF | |
| Security an | nd Facilitations | | |
| | Hand Held /Walk Through Metal Detector | Yes | |
| Meteorological Service | | Tower Observation | |
| Electro-Mechanical Facilities | | | |
| | Power Supply | Yes (3 Phase & Solar Supply) | |
| | Runway Threshold Light | Yes at RWY 34 | |
| | Runway End Light | Yes at RWY 16 | |
| | PAPI | Yes | |
| | Stand -by-supply | Solar, Inverter, Generator | |
| | Air Conditioner | Yes | |
| Rescue an | d Fire-Fighting Services | Yes | |

Financial Overview (Income & Expenditure)


| Fiscal Year | Income(NPR) | Expenses(NPR) |
|-------------|--------------|---------------|
| 2072/073 | 1,936,831.59 | 6,012,261.56 |
| 2073/074 | 2,220,533.54 | 8,668,507.20 |
| 2074/075 | 2,180,621.24 | 7,574,347.19 |
| 2075/076 | 3,003,871.59 | 13,523,191.45 |
| 2076/077 | 2,088,300.14 | 4,263,430.99 |
| 5Yr AVG | 2,286,031.62 | 8,008,347.68 |




Note: Expenses do not include Staff Expenses and Expenses Directly incurred by Head Office.



Tumlingtar Flight Movement Comparison 2016-2020





* Data 2020 (upto November)

Profile Edited on: 30 December, 2020